

TÜV-SÜD Product Service, Octagon House, Concorde Way, Segensworth North, Fareham, Hampshire, United Kingdom, PO15 5RL Tel: +44 (0) 1489 558100

Website: www.tuv-sud.co.uk

COMMERCIAL-IN-CONFIDENCE

TEST HOUSE CERTIFICATE

CLIENT **Daniamant Limited**

Unit 3. The Admiral Park Airport Service Road Portsmouth, Hampshire United Kingdom PO3 5RQ

DOCUMENT

75929303 THC 01 Issue 2

CLIENT'S ORDER NUMBER

PC0001458, dated 02.02.2015

INCOMING RELEASE NOTE

DATE OF RECEIPT

EQUIPMENT UNDER TEST (EUT)

MODEL/PART NUMBERS(S)

Not Released

10 February 2015

Survivor Location Lights, as stated below (x9 units tested)

	Description	Model	TSR № *
1	External Raft Light	Rescue Master 2B	001
2	Lifebuoy Light	L170	002
3	Lifebuoy Light	L160	003
4	Lifebuoy Light	L161	004
5	Lifebuoy Light	L162	005
6	Lifebuoy Light	L163	006
7	Hand Held LED Distress Flare	ODEO Mk.3	007
8	Lifebuoy Light	L90	800
9	Life Raft External Light	RL6	009
* Test Sample Registration Number			

TEST SPECIFICATION / ISSUE EN 60529:1992. Table III, Table VIII and clause 14.2.7.

DEVIATIONS FROM THE STANDARD

DATE OF TEST 11 February 2015

TEST(S) DESCRIPTION

Protection Against Ingress by Immersion in Water (IPX7)

The following test was required by the specification:

- 1. Immediately prior to the test examine each EUT. Manually switch each EUT to ON and OFF.
- 2. Immerse each EUT in water so that the lowest point of the EUT is 1000 mm below the surface of the water, and for a duration of 30 mins.

None

3. On completion of the test re-examine the units. Note any conspicuous ingress of water. Manually switch each EUT to ON and OFF.

RESULT(S) OF TEST

The test requirements were satisfied. No water ingress, other damage or detrimental effects were observed or reported during or on completion of the test. When switched ON after the test all lights operated and/or flashed satisfactorily as required and as compared to the operation prior to the test. Items 1 and 9 required the connection of an external battery source before they were operated.

This certificate relates only to the actual item/items tested.

This THC has been up-issued to Issue 2 to correct an incorrect description applied to item 9 (RL6 unit)

Approved by

Authorised Signatory



Date 4 March 2015